

APPENDIX 3– ESTIMATION OF QUANTITY

No	Description	Quantity*		Unit Price (IDR)	Total Price (IDR)
1	Removal of Existing Glass Frames, Frames and accessories	303.9	sqm	-	-
2	Supply and Install Glass Canopy, Steel Frames and accessories	303.9	sqm	-	-
3	Column Repair by epoxy resin Injection	77	unit	-	-
4	Beam Repair by epoxy resin Injection	80	unit	-	-
5	tightening of existing bolts to meet the specified torque requirements	600	unit	-	-
6	Repainting of Steel Structure	1	lot	-	-
7	Repair / Replacement of Steel Frame (if necessary)	1	lot	-	-
8	Mobilization & Demobilization, Scaffolding, supporting tools, construction barriers and safety tools	1	lot	-	-
					-
*)	<i>This table is only for information. The contractor must conduct their own measurements during the site visit to ensure accuracy in determining quantities.</i>				